

Message

From: Crossland, Ronnie [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=4B8595BD12E84048A4E646ABA3FED108-CROSSLAND, RONNIE]
Sent: 3/19/2019 8:36:42 PM
To: Gray, David [gray.david@epa.gov]
Subject: FW: Thank You

David,

Here is the email from TCEQ regarding one of their air monitors.

Thanks
Ronnie

From: Kelly Cook <kelly.cook@tceq.texas.gov>
Sent: Tuesday, March 19, 2019 3:26 PM
To: Crossland, Ronnie <Crossland.Ronnie@epa.gov>
Subject: Fwd: Thank You

Sent from my iPhone

Begin forwarded message:

From: Tracy Miller <tracy.miller@tceq.texas.gov>
Date: March 19, 2019 at 10:09:37 AM CDT
To: Kelly Cook <kelly.cook@tceq.texas.gov>
Subject: RE: Thank You

Should I give this info to Lorenzo to share right now or should we incorporate it into the HSNotify update that he will share?

From: Kelly Cook
Sent: Tuesday, March 19, 2019 10:06 AM
To: Tracy Miller <tracy.miller@tceq.texas.gov>
Subject: Thank You

Thank You.

From: Tracy Miller
Sent: Tuesday, March 19, 2019 9:57 AM
To: Kelly Cook <kelly.cook@tceq.texas.gov>
Cc: Richard Chism <Richard.Chism@tceq.texas.gov>; Brandy Brooks <brandy.brooks@tceq.texas.gov>; Ramiro Garcia <ramiro.garcia@tceq.texas.gov>; Susan Johnson <susan.johnson@tceq.texas.gov>
Subject: FW: Non functioning air monitor

FYI - This information was provided to media relations last night to share

From: Ramiro Garcia
Sent: Monday, March 18, 2019 5:22 PM

To: Martha Otero <Martha.Otero@tceq.texas.gov>; Brandy Brooks <brandy.brooks@tceq.texas.gov>
Cc: Richard Chism <Richard.Chism@tceq.texas.gov>; Susan Johnson <susan.johnson@tceq.texas.gov>;
Tracy Miller <tracy.miller@tceq.texas.gov>
Subject: RE: Non functioning air monitor

Hello Martha, Brandy and Cory,

DRAFT RESPONSE FOR YOUR REVIEW

I summarized Brandy's findings related to the Deer Park – CAMS 35 Monitor.

Brandy and Cory Please review the draft response to make sure I did not leave anything off. Please feel free to edit.

Martha – Once the final review is completed you will be clear to send to the reporter. Thank you.

The TCEQ ambient monitoring station at Houston Deer Park (CAMS 35) experienced operational issues with the AutoGC sampler, indicated by quality control failures on March 11. Therefore, data were invalidated back to the previous passing daily QC check which was March 10. Only the AutoGC was affected; other samplers at this monitoring station continued to operate normally.

The TCEQ contractor performed the repair March 13-16. Following this repair, the contractor must run a 1-point QC check, followed by a multi-point check typically completed within a few days. The instrument passed the 1-point QC check at 8:00 am on Saturday, March 16. The instrument resumed ambient data collection at 11:00 am on Saturday, March 16, the day before the fire.

The instrument continued to collect ambient data throughout the day on Sunday, March 17 and into Monday, March 18 until 5:00 am. The contractor began the multi-point check at 6:00 am on Monday, March 18, this QC check is required in the days following a repair.

The multi-point check was completed and ambient data collection has resumed as of 1:00 pm, Monday, March 18.

The ambient data collected from Saturday, March 16 through early Monday, March 18 have undergone preliminary review and are within required quality standards.

The valid ambient AutoGC data collection resumed at 1:00 pm CST and data appears ambient and consistent with normal trends.

From: Martha Otero
Sent: Monday, March 18, 2019 2:47 PM
To: Brandy Brooks <brandy.brooks@tceq.texas.gov>
Cc: Richard Chism <Richard.Chism@tceq.texas.gov>; Ramiro Garcia <ramiro.garcia@tceq.texas.gov>
Subject: Non functioning air monitor

Brandy,

I know you are working on a reply to this but wanted to send it for the record.

Reporter is asking about monitor that is not working in Deer Park – 35 CAMS).

thanks

Marty Otero

TCEQ Media Relations Specialist
512-239-0046 phone
Office Hours 8:00 am to 5:00 pm

Follow us on Twitter @TCEQ

